A SHUTTER MISLATCH OCCURRED AND INVOLVES FRAMES 093 AND 094 METERING SLIGHTLY ERRATIC THRU-OUT, NO OVERLAPS NOTED. GHOSTING OF THE ADJACENT POSITION INDICATOR LAMPS IS NOTICABLE VERTICAL INDICATOR WHILE THE CORRECT POSTION LAMP IS EXPOSED. DOT IS SLIGHTLY OVEREXPOSED AND BLOSSOMED. PRESSURE ROLLER STATIC (CHATTER) IS NOTED ALONG THE INBOARD EDGE OF BOTH 9L AND 9 R FILM AND ONLY SLIGHTLY ALONG THE INTERMITTANT SMALL FOG PATCHES OUTBOARD EDGE OF THE 9R SIDE. OCCUR ALONG THE OUTBOARD EDGE OF THE 9L FORMAT AREA. THESE PATCHES ARE MINOR, POSSIBLY A FORMAT FRAME REFLECTION, IS NOTED ON AND APPROX. 1.5 INCHES IN DIAMETER. A SCRATCH THIS SCRATCH BEGINS FRAMES 2381 THRU THE MIDDLE OF 3716. THERE IS A QUALITY DROP

AT AN EMULSION LIFT ON FRAME 2381. THERE IS A QUALITY DROP OFF TOWARD ALL OUTBOARD CORNERS. SEVERAL OF ABOVE COMMENTS WERE ALSO MENTIONED IN REF. PARA C.

-END OF MSG-

8.

(,,

GOOD

TOPSECRET